


Bank Stability and Composition on the Connecticut River in northern Brunswick, VT



MAP LEGEND

Bank Stability		
—	—	Channelization
—	—	High eroding banks
—	—	Sediment inputs from tributaries
—	—	Undifferentiated
—	—	Moderate Erosion
—	—	Stable
—	—	Rip Rap
—	—	Old Rip Rap
Bank Composition		
—	—	Alluvial
—	—	Nonalluvial
—	—	Bedrock

Locator Map

Bloomfield VT
Brunswick VT
Maidstone VT
Stratford NH

Enlarged map area

0 1500 3000 Feet



Map prepared by:



With support from:



Map source: Basemap - USGS DRG quads, VCGI 2004
Field survey data - Field Geology Services 2004
Map Prepared December 2005